ANTI-LOCK BRAKE SYSTEMS

- Hydraulic and control units that are broken, cracked or damaged: NO CORE CREDIT
- Disassembled units: NO CORE CREDIT
- Missing or damaged electrical motors or accumulators:
 50% LESS CREDIT
- Cut harnesses or broken connector plugs:
 25% LESS CREDIT
- Missing connector pins on ECU: NO CORE CREDIT
- Bent connector pins on ECU: 25% LESS CREDIT
- Missing fittings or bleeder valves, or with fittings or bleeder valves broken off in casting: 25% LESS CREDIT

POWER BRAKE UNITS

ALL UNITS

- Units that are worn, broken, scored, damaged, cracked, frozen or rusted: NO CORE CREDIT
- Incomplete or disassembled: NO CORE CREDIT
- Broken or missing plastic hub: 25% LESS CREDIT
- Missing check valve: 20% LESS CREDIT

LOADED DOMESTIC AND HYDRO-VAC

- All domestic vacuum power brake units returned with out the master cylinder/slave cylinder attached:
 50% LESS CREDIT
- Domestic units returned without master cylinder lids:
 5% LESS CREDIT
- Missing pedal rod: 25% LESS CREDIT
- Broken hub: 25% LESS CREDIT




UNLOADED DOMESTIC AND IMPORT

 Units returned with missing output rod (between the master cylinder & power brake) and/or missing pedal rod:
 25% LESS CREDIT



FRICTION CHOICE/BOLT-ON READY CALIPERS

- Castings that are worn, broken, scored, damaged, cracked, frozen or rusted: NO CORE CREDIT
- Missing bracket/yokes (where applicable):
 50% LESS CREDIT
- Damaged or missing pistons: 50% LESS CREDIT
- Missing pad hardware or small parts: 25% LESS CREDIT





MASTER CYLINDERS

- Castings that are worn, broken, scored, damaged, cracked or frozen: NO CORE CREDIT
- Disassembled units: NO CORE CREDIT
- Units returned with broken or missing lids:
 10% LESS CREDIT



CONSTANT VELOCITY DRIVE AXLES

- Disassembled units: NO CORE CREDIT
- Missing outer CV Joint: NO CORE CREDIT



4x4 DRIVESHAFTS & PROP SHAFTS

• Standard core policy rules apply. (See cover page).

DISTRIBUTORS

- Housings that are worn, broken, scored, damaged or cracked: NO CORE CREDIT
- Broken plastic housing (30-1636, 1639, 1829, 1878):
 50% LESS CREDIT
- Any shafts broken: 50% LESS CREDIT
- Completely disassembled units: NO CORE CREDIT

- Missing HEI module: 50% LESS CREDIT
- Missing Hall Effect switch: 50% LESS CREDIT
- Missing Fuel Injector harness (30-1800, 1801, 1808):
 50% LESS CREDIT
- Missing Electronic plate (30-3491, 3493):
 50% LESS CREDIT
- Missing Fuel Injector harness (30-1800, 1801, 1808):
 50% LESS CREDIT
- Missing Electronic plate (30-3491, 3493):
 50% LESS CREDIT



DIESEL INJECTORS & PUMPS TURBOCHARGERS/SUPERCHARGERS

- Missing fittings or fittings broken off in casting:
 90% LESS CREDIT
- Turbocharger cores with obvious compressor or turbine wheel damage: 90% LESS CREDIT
- Obvious external damage or missing components:
 90% LESS CREDIT
- Disassembled units: 90% LESS CREDIT
- Cut harnesses or broken/missing actuators, connector plugs, or sensors: 90% LESS CREDIT
- Missing or damaged electrical components:
 90% LESS CREDIT
- Bent, broken, cracked, rusted, burnt or water damaged parts: NO CORE CREDIT
- The OEM Service Label must be in place and legible on Module units for core credit.

ENGINE CONTROL MODULE/BODY CONTROL COMPUTER

- Cracked, rusted, corroded, fire damaged, water damaged or missing circuit board: NO CORE CREDIT
- Cracked, broken, burnt or damaged case:
 50% LESS CREDIT
- OEM Service Label must be in place and legible on the unit (see illustration). TYPICAL GM ORIGINAL EQUIPMENT LABEL REMANUFACTURED





ELECTRONIC THROTTLE BODIES

- Cracked, rusted, corroded, fire damaged, water damaged: NO CORE CREDIT
- Disassembled units: NO CORE CREDIT
- Broken connector and/or broken plastic parts:
 50% LESS CREDIT
- Missing components: 50% LESS CREDIT
- Damaged, bent or missing ports: 50% LESS CREDIT

ELECTRONICS

CRUISE CONTROL

Disassembled units: NO CORE CREDIT

TRANSDUCERS

- Housings that are broken, damaged, cracked, frozen or rusted: NO CORE CREDIT
- Missing filter cover: 50% LESS CREDIT

SERVOS

- Broken/missing plastic vacuum ports:
 50% LESS CREDIT
- Cracked/broken plastic housing or diaphragm base:
 50% LESS CREDIT
- Broken or missing terminals: 50% LESS CREDIT
- Damaged or missing bracket: 50% LESS CREDIT
- Damaged, cut or missing harness (Ford units):
 50% LESS CREDIT

MODULES

- Cracked, rusted, corroded, fire damaged, water damaged or missing circuit board: NO CORE CREDIT
- Cracked, broken, burnt or damaged case:
 50% LESS CREDIT

MASS AIRFLOW SENSORS/VANE AIRFLOW METERS

- Crushed, disassembled, water or fire damaged parts:
 NO CORE CREDIT
- Damaged or missing module: NO CORE CREDIT
- Screen damaged or broken: 75% LESS CREDIT
- Housing or plastic connector cracked, broken or dented:
 75% LESS CREDIT




6

SMOG AIR PUMPS

- Disassembled units: NO CORE CREDIT
- Electronic units with cracked housing:
 50% LESS CREDIT

WATER PUMPS

- Disassembled units: NO CORE CREDIT
- Broken housing: NO CORE CREDIT



VACUUM PUMPS

- Disassembled units: NO CORE CREDIT
- Broken Housings: NO CORE CREDIT



TRANSFER CASE MOTORS

- Housings that are worn, broken, scored, damaged, cracked, frozen or rusted: NO CORE CREDIT
- Broken terminal connector and/or broken plastic parts:
 50% LESS CREDIT
- Missing bracket: 30% LESS CREDIT
- Disassembled units: NO CORE CREDIT
- Broken cover (48-201, 48-202, 48-203, 48-204, 48-205, 48-206, 48-207): 70% LESS CREDIT

ELECTRICAL MOTORS

- Housings that are worn, broken, scored, damaged, cracked, frozen or rusted: NO CORE CREDIT
- Broken terminal connector and/or broken plastic parts:
 50% LESS CREDIT
- Broken washer pump cover and/or missing washer pump component parts (40-1681, 40-1682, 40-901, 40-902): 50% LESS CREDIT
- Broken washer nozzles on rear wiper motors:
 50% LESS CREDIT
- Disassembled units: NO CORE CREDIT
- Missing bracket or broken cover on all part numbers with an "R" or "L" suffix: 50% LESS CREDIT



POWER STEERING PUMPS

- Completely disassembled core or broken casting:
 NO CORE CREDIT
- Broken reservoir: 25% LESS CREDIT
- Missing banjo fittings, banjo fitting valves, springs:
 25% LESS CREDIT
- Missing (EVO) Electronic Variable Orifice:
 50% LESS CREDIT
- EPS/EHPS (Electro-Hydraulic Power Steering) cores with cut harnesses or broken terminal connector:
 50% LESS CREDIT
- EPS cores with broken plastic reservoir:
 50% LESS CREDIT






POWER STEERING GEARS

- Housings that are worn, broken, cracked or rusted:
 NO CORE CREDIT
- Disassembled units: NO CORE CREDIT
- Broken sector shaft: 50% LESS CREDIT
- Broken or missing input valve assembly:
 50% LESS CREDIT



RACK AND PINION

- Housings that are worn, broken, scored, damaged, cracked, frozen or rusted: NO CORE CREDIT
- Bent rack: NO CORE CREDIT
- Missing Rack: NO CORE CREDIT
- Missing Pinion Valve Assembly: NO CORE CREDIT
- Disassembled units: NO CORE CREDIT
- Missing inner tie rods**: 30% LESS CREDIT (each)
- Missing EVO (with "E" suffix): 50% LESS CREDIT
- EPS cores with cut harness or broken terminal connector: 50% LESS CREDIT
- ** DOES NOT APPLY TO "SHORT RACK"





CORE POLICIES AND WARRANTY DEDUCTIONS

All cores must be returned in the original box to receive **FULL CORE CREDIT**

All cores not returned in the box receive

MAXIMUM 10% CORE CREDIT

Core credit allowed only for units in the current programs

ONLY EXCHANGE CORES ACCEPTED FOR CORE CREDIT

CARDONE

5501 Whitaker Avenue Philadelphia, PA 19124-1799

www.cardone.com

215-912-3000